

**From:** [Nancy Jones](#)  
**To:** [patrick.d.wycko@uscg.mil](mailto:patrick.d.wycko@uscg.mil)  
**Cc:** [R6 DWH Info@EPA](#)  
**Subject:** Fw: Corexit 9500 and 9527 MSDS  
**Date:** 05/14/2010 08:39 AM  
**Attachments:** [Corexit 9527 MSDS.pdf](#)  
[COREXIT 9500 UsCuEg.pdf](#)

---

----- Forwarded by Nancy Jones/R6/USEPA/US on 05/14/2010 08:37 AM -----

## Corexit 9500 and 9527 MSDS

**Byrum,** to: Philip Campagna  
**Alex**

05/11/2010  
04:51 PM

Cc: Joe Schaefer, Nancy Jones

---

Phil,

I have attached the MSDS for the two dispersants being used for aerial application. The 9527 has the 2-Butoxyethanol, which is causing problems for the state of Louisiana. Ops here are going to stop using the 9527 since they are not going to have any more after the 14<sup>th</sup> of May. The 9500 has petroleum distillates and propylene glycol, which I guess are the chemical constituents of concern for 9500.

Basically, they want to know what we would use to sample and monitor for dispersants.

Thank you

Alex J. Byrum  
Project Scientist  
Weston Solutions, Inc.  
14160 Dallas Parkway, Suite 850  
Dallas, Texas 75254  
(469) 374-7760 work  
(214) 868-3966 cell

CONFIDENTIALITY: This email and attachments may contain information which is

confidential and proprietary. Disclosure or use of any such confidential or proprietary information without the written permission of Weston Solutions, Inc. is strictly prohibited. If you received this email in error, please notify the sender by return e-mail and delete this



email from your system. Thank you. [Corexit 9527 MSDS.pdf](#) [COREXIT\\_9500\\_UsCuEg.pdf](#)